

## 1. INSURANCE EVENTS

**Event #1**

**2017-12-29**

### Vehicle

Model: A3/S3 SDN 05/13-06/16 (8V) [V] [S] [3D] [5A]

VIN: WOL000075T4284102

### Insurance event:

Country	Czech republic	Insurance event date:	-
The author:	Garage	Type of loss event	-
Calculation with alternatives	-	Last calculation date:	2017-12-29


### Vehicle data:

Date of first registration:	-	Engine:	-
Date of last registration:	-	Mileage:	-
Color	-	Power	-
Engine capacity	-		

### Repair price:

Work:	2467.50 CZK
Spare parts:	7733.32 CZK
Painting costs:	- CZK
Price for painting:	- CZK
Painting material:	- CZK
Total cost:	10200.82 CZK
Total cost + Participation	10200.82 CZK

### Damage location



### List of repaired parts:

Description of spare parts	Operation
GLASS-SET OF FRONT-GLASS	part replacement for new
CLEANING SOLUTION	part replacement for new
WIRE TO REMOVE THE GLASS	part replacement for new
APPLICATOR	part replacement for new
PRIMER OF GLASS	part replacement for new
ADHESIVE FOIL MOISTURE VZD	part replacement for new
FRONT GLASS	part replacement for new
FRONT GLASS	part replacement for new
CLEANING SOLUTION	part replacement for new
PRIMER OF GLASS	part replacement for new



---

ADHESIVE FOIL MOISTURE VZD      part replacement for new

---

APPLICATOR      part replacement for new

---

WIRE TO REMOVE THE GLASS      part replacement for new

---

GLASS-SET OF FRONT-GLASS      part replacement for new

---



## Event #2

2016-11-10

## Vehicle

Model: A3/S3 SDN 05/13-06/16 (8V) [V] [S] [3D] [5A]

VIN: W0L000075T4284102

## Insurance event:

Country	Germany	Insurance event date:	-
The author:	Garage	Type of loss event	-
Calculation with alternatives	-	Last calculation date:	2016-11-11


## Vehicle data:

Date of first registration:	-	Engine:	-
Date of last registration:	-	Mileage:	12415
Color	Weiss 2c	Power	-
Engine capacity	-		

## Repair price:

Work:	- EUR
Spare parts:	- EUR
Painting costs:	216.20 EUR
Price for painting:	81.00 EUR
Painting material:	135.20 EUR
Total cost:	216.20 EUR
Total cost + Participation	432.4 EUR

## Damage location



## List of repaired parts:

Description of spare parts	Operation
BUMPER COVER B	painting of new part (different painting methods)
SENSOR HOLDER VN Z P	painting of the original part
SENSOR HOLDER VN Z L	painting of the original part



## Event #3

2015-09-04

## Vehicle

Model: A3/S3 SDN 05/13-06/16 (8V) [V] [S] [3D] [5A]

VIN: W0L000075T4284102

## Insurance event:

Country	Slovakia	Insurance event date:	2015-09-01
The author:	-	Type of loss event	-
Calculation with alternatives	AlternativeParts	Last calculation date:	2015-09-04


## Vehicle data:

Date of first registration:	-	Engine:	-
Date of last registration:	-	Mileage:	-
Color	-	Power	-
Engine capacity	-		

## Repair price:

Work:	55.01 EUR
Spare parts:	354.13 EUR
Painting costs:	242.94 EUR
Price for painting:	63.35 EUR
Painting material:	179.59 EUR
Total cost:	652.08 EUR
Total cost + Participation	895.02 EUR

## Damage location



## List of repaired parts:

Description of spare parts	Operation
WIRE TO REMOVE THE GLASS	part replacement for new
PRIMER	part replacement for new
FRONT GLASS	part replacement for new
ADHESIVE FOIL	part replacement for new
ENGINE-HOOD, ENGINE COVER	part replacement for new
GLASS-SET OF FRONT-GLASS	part replacement for new
ENGINE-HOOD, ENGINE COVER	painting of new part (different painting methods)
UPEV-SADA PRED-SKLA	part replacement for new
SPACING PIECE	part replacement for new
ACTIVATOR FRONT GLASS	part replacement for new

## Event #4

2015-03-19

## Vehicle

Model: A3/S3 SDN 05/13-06/16 (8V) [V] [S] [3D] [5A]

VIN: W0L000075T4284102

## Insurance event:

Country	Hungary	Insurance event date:	2015-01-27
The author:	-	Type of loss event	-
Calculation with alternatives	-	Last calculation date:	-

## Vehicle data:

Date of first registration:	-	Engine:	-
Date of last registration:	-	Mileage:	129647
Color	-	Power	-
Engine capacity	2400		

## Repair price:

Work:	3000.00 HUF
Spare parts:	164249.00 HUF
Painting costs:	- HUF
Price for painting:	- HUF
Painting material:	- HUF
Total cost:	167249.00 HUF
Total cost + Participation	167249 HUF

## Damage location





## List of repaired parts:

Description of spare parts	Operation
----------------------------	-----------



## 2. VEHICLE THEFT VERIFICATION

 Slovak republic (Police)	FOUND	 Germany (Kaynine)	NOT FOUND
 Czech republic (Police)	NOT FOUND	 Netherlands (Kaynine)	NOT FOUND
 Republic of Slovenia (Police)	NOT FOUND	 Belgium (Kaynine)	NOT FOUND
 Lithuania (Police)	NOT FOUND		
 Hungary (Police)	NOT FOUND		
 Romania (Police)	NOT FOUND		

## 3. EUROPEAN CAR CODE REGISTER

The VINPRINT system marks windshields of vehicles using etching method in 4 countries CZ, SK, AT, HU.

Mechanical security	NO
VIN Assistance	NO
Home service	-

Date and time	Number of copies	Company name	Office	City
20.12.2016 9:20	6	Auto Palace Bratislava	Auto Palace Bratislava	Bratislava

## 4. VIN DECODER

<b>Make:</b>	Opel	<b>Manufacturer:</b>	Adam Opel AG
<b>Plant Country:</b>	Germany	<b>Product Type:</b>	Passenger car
<b>Manufacturer Address:</b>	Bahnhofspatz, 65423 Ruesselsheim, Germany	<b>Check Digit:</b>	5
<b>Sequential Number:</b>	284102	<b>Model Year:</b>	1996
<b>Transmission:</b>	Manual/Standard	<b>Model:</b>	Tigra
<b>Series:</b>	S93 COUPE	<b>Fuel Type - Primary:</b>	Gasoline
<b>Engine Displacement (ccm):</b>	1389	<b>Body:</b>	Coupe
<b>Engine Power (kW):</b>	67	<b>Engine RPM:</b>	6000
<b>Number of Doors:</b>	2	<b>Engine Cylinders Position:</b>	Inline
<b>Drive:</b>	Front-wheel drive	<b>Length (mm):</b>	3922
<b>Height (mm):</b>	1340	<b>Engine Cylinders:</b>	4
<b>Width (mm):</b>	1604	<b>Fuel System:</b>	Multi-point injection
<b>Engine Torque:</b>	125	<b>Wheelbase (mm):</b>	2429
<b>Engine Position:</b>	Front, transversely	<b>Fuel Capacity:</b>	46
<b>Weight Empty (kg):</b>	980	<b>Front Breaks:</b>	Disc
<b>Rear Breaks:</b>	Drum	<b>Valves per Cylinder:</b>	4
<b>Track Front (mm):</b>	1387	<b>Track Rear (mm):</b>	1388
<b>ABS:</b>	1	<b>Wheel Size:</b>	185/55 R15



<b>Engine Compression Ratio:</b>	10	<b>Steering Type:</b>	Steering rack
<b>Engine Stroke:</b>	73.4	<b>Engine Cylinder Bore:</b>	77.6
<b>Minimum volume of Luggage (trunk):</b>	215	<b>Max Weight (kg):</b>	1330
<b>Production Stopped:</b>	2001	<b>Production Started:</b>	1994
<b>Front Suspension:</b>	Helical spring	<b>Rear Suspension:</b>	Trailing
<b>Valve Train:</b>	DOHC	<b>Power Steering:</b>	Hydraulic Steering
<b>Maximum volume of Luggage (trunk):</b>	425	<b>Wheel Rims Size:</b>	R15

## 5. EXPERT VALUE OF VEHICLE

<b>Value of new vehicle with VAT</b>	from 15996 €	to 23029 €
<b>Average value of new vehicle</b>	19513 €	
<b>The current market value of the vehicle</b>	572 €	

